

9241414
Kenworth/Peterbilt Condenser
Product Note



Check the condenser bottom bracket as compared to the unit removed from the truck. If the removed unit looks like the unit shown in the above illustration, proceed to check the truck for hood brace clearance with the hood closed and the old unit bolted in position. If required cut and notch the replacement bracket accordingly.